

Beam detectors are an important component of any accelerator. The type of detectors needed in a certain accelerator and their requirements follow in part from user requirements and in part from machine requirements, such as its protection. While some general considerations will be made for all types of accelerators, the diagnostics at FLASH will be mostly shown. Issues related to the machine operation will also briefly be addressed.